

Received: 2/18/02 17:00;

-> PORTER INSTRUMENT CO 13 PAG 6343 E

02-18-02 16:41 FROM-RATNER & PRESTIA

6104070701

T-246 P.043/056 F-983




FIG. 1

10007709 022302





FIG. 2

FIG. 3



Received: 2/18/02 17:01;


> PORTER INSTRUMENT CO.; Page 46 of 47

02-18-02 16:41 FROM-RATNER & PRESTIA

6104070701

T-246 P-046/056 F-983

FIG 4



16

FIG. 5.






FIG. 6B

FIG. 6A

Received: 2/18/02 17:01;

-> PORTER INSTRUMENT CO., INC. PAGE 26 OF 27

02-18-02 16:42 FROM-RATNER & PRESTIA

6104070701

T-246 P.048/056 F-983





FIG. 7

FIG. 8



Received: 2/18/02 17:01;

02-18-02 16:42 FROM-RATNER & PRESTIA

-> PORTER INSTRUMENT CO. Page 60

6104070701

T-246 P.050/056 F-983




Fig. 9




Fig. 10A




Fig. 10B




FIG 11.

Received: 2/18/02 17:02;

02-18-02 16:42 FROM-RATNER & PRESTIA

-> PORTER INSTRUMENT CO INC DULUTH MN

6104070701

T-246 P.054/056 F-983





Fig. 12



Received: 2/18/02 17:02;

-> PORTER INSTRUMENT CO., INC. Page 56

02-18-02 16:43 FROM-RATNER & PRESTIA

6104070701

T-246 P.056/056 F-883

94F




Fig. 14

